

Shenzhen Huahui Precision Machinery Technology Co., Ltd.

ADD: No. 40, Third Industrial Zone, Houting Community, Shajing Street, Bao'an District, Shenzhen
Tel : +86-0755-85263366



INSPECTION REPORT

Clients

STREPARAVA S.P.A

Part No.

412-38-011

REMARQUES

Quantity:30PCS

Requirement: All parts, all dimensions, 100% full inspection

No.	Dimension Item	Nominal / Standard	Tolerance	Measured Value	Result	Measurement Tool	Remarques et actions
1	Overall length	1.250	±0.005	1.251	OK	Caliper	
2	Width	0.375	+0 / -0.001	0.3746	OK	Micrometer	
3	Hole Ø	Ø0.0622	+0.0004 / -0	0.0624	OK	Pin gauge	
4	Width	0.4375	+0.0005 / -0	0.4377	OK	Micrometer	
5	Width	0.431	±0.001	0.4312	OK	Micrometer	
6	Width	0.375	±0.001	0.3751	OK	Micrometer	
7	Height	0.156	±0.001	0.1558	OK	Micrometer	
8	Height	0.260	+0.005 / -0	0.2620	OK	Micrometer	
9	Hole Ø	Ø0.5000	+0.0005 / -0	0.5002	OK	Bore gauge	
10	Angle	30°	±30 min	30.0°	OK	Angle gauge	
11	Angle	15°	±30 min	15.0°	OK	Angle gauge	
12	Chamfer	.03 x 45°	As drawing	.03 x 45°	OK	Visual / Caliper	

Prepared by: 熊蜂

Inspector: 李新发

Supervisor: 陈保坤

Date: 2026-05-25

